


Checklist for a Perfect Fit



1. Are there pressure points on the side of the head or behind the ears?
2. Does the nose piece make contact without pinching?
3. Can you see clearly in all directions without major obstruction?
4. Is the overall weight of your safety eyewear evenly distributed between your ears?
5. Does your eyewear fit close to your face without hitting your eyelashes? Gaps should be less than or equal to 6-8mm, depending on your work environment.
6. Does your eyewear cover your eyebrow and any soft tissue around it?
7. Can you move your head front to back and tilt your head side to side without your eyewear shifting out of place?